

SURVEY & REMONUMENTATION

OTTAWA COUNTY REMONUMENTATION

OCT 07 1996

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

For corner of **COMMISSION**
OTTAWA
 (County)

	Located In:	Corner Code #
1. Public Land Survey	T <u>6N</u> R <u>13W</u>	I-5 (SE corner Section 10) Georgetown Twp.
	T _____ R _____	
	T _____ R _____	
	T _____ R _____	
2. Property Controlling in Section	S _____ T _____ R _____	
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	

96 AUG 26 PM 2:02

R. J. Vugteveen
 REGISTER OF DEEDS
 OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Randal J. Vugteveen, in a field survey on October 19, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
 I-5 Common corner to Sections 10, 11, 14 & 15

1831 - Sibley	1960 - County Surveyor
Set post	S 33' to 24" Elm
W. Oak N82 W25 14 Links	N 75 deg E to wit Y in 10" Elm
Pine S66 E28 7 Links	Fences to W, S, E & N

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 I-5 Found conc mon (broken top) 55' SW of Broadview Dr centerline 142' SE of Ronson Ave and accepted as a careful and faithful perpetuation of the position of the original corner


Found conc. mon N 29.65'	This corner was a plat corner monument and
Found Nail in S side 12" Oak East 19'	has been held for numerous plats including
Found Nail in E side 28" Oak South 33'	Broadview Gardens - Broadview Gardens No. 9
	S 33' 32" Oak

P.A. 345 OTTAWA COUNTY
 PEER APPROVED 12/11/95

Randal J. Vugteveen

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 I-5 Removed conc mon, set 3/4" X 36" solid bar with Ottawa County Remon cap

- Set Ottawa County Remon Nail & Tag in N side 12" Oak East 18.74'
- Set Ottawa County Remon Nail & Tag in E side 32" Oak South 33.07'
- Set Ottawa County Remon Nail & Tag in S side 14" Elm West 9.78'
- NE corner garage #8000 Ronson S80W 19.35'
- NW brick corner garage #1574 Broadview Dr. S30E 62.14'



Signed by *Randal J. Vugteveen*
 Surveyor's Michigan License No. 28429

Date Dec 11, 1995