

82

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Schoolcraft

(County)

Located in:

Corner Code #

1. Public Land Survey

T 47N R 14W \_\_\_\_\_ E13 \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

2. Property Controlling  
in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

3. Miscellaneous  
Property in Sec.

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_ \_\_\_\_\_

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Jul 03 1997

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 19\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

**A. Description of original monument and accessories and/or subsequent restoration:**

(E13) Corner common to Sections 32-33 T47N-R14W and Sections 4-5 T46N-R14W. Corner remonumented in 1953 by Michigan Dept. of Conservation surveyor Dean C. DeLaMater, RLS: "This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Two original B.T.'s still in place, in fair condition. Corner monument: 1" Pipe with 4" brass cap. Witnesses to corner: 10" J. Pine N31W 92 links, 5" W. Birch S18W 56 links".

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(E13) Found the 1953 monument as described, a 1" I.D. iron pipe capped with a 4" brass Michigan Dept. of Conservation tablet, in good condition. The 1954 witnesses were not recovered. Left the monument in place and marked four new accessories as described below. No measurements to other corners were made at this time. This corner is being rerecorded in order to update the accessories. Corner recovered and re-witnessed by T. Stark, Newberry District Office, MDNR. Placed a location tag on a 3" J. pine 15' north of road and 172' south of the corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(E13) Found 1" pipe with 4" brass cap. Blazed, scribed, and set measuring nails in the following:


6" J. Pine S56W 8.8' "S5 NBT"

6" Twin R. Pine N54W 40.4' "S32 NBT"

5" J. Pine N67E 85.45' "S33 NBT"

6" J. Pine S07E 90.65' "S4 NBT"

Placed a 5" squared and scribed cedar post adjacent. Bearings are magnetic.



Signed by

*Stephan J. Szyszkoski*

Date

9/3/97

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1985