

2014 STATE OF MICHIGAN, PRESQUE ISLE COUNTY REMONUMENTATION Received

PRESQUE ISLE COUNTY
01-09-2015 09:11 am.

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Instrument 201500000115 OR
Liber Page 558 983

Presque Isle (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>33N</u> R <u>08E</u>	<u>I-10</u>
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

201500000115
Filed for Record in
PRESQUE ISLE COUNTY
CATHY I. IDALSKI, REG OF DEEDS
01-09-2015 At 09:21 am.
LC-REMON 17.00
OR Liber 558 Page 983 - 984
Register of Deeds Stamp & Figure Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Travis L. Horrocks, in a field survey on June 23, 2014 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.


	A	B	C	D	E	F	G	H	I	J	K	L	H
1													
2	5	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	10	11	12	13	14	15							
7													
8	13	14	15	16	17	18							
9													
10	16	17	18	19	20	21							
11													
12	19	20	21	22	23	24							
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-10
SEE BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-10
FD. 1/2" ROD, NORTH 160' & WEST 48'
TO THUNDER BAY RIVER
N 43° W 14.53' 50" MAPLE #15410
N 08° E 21.14' 43" MAPLE #15410
N 37° E 22.60' 20" MAPLE #15410
S 15° W 20.56' 16" DEAD ASH #15410



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-10
1/2" ROD & REMON CAP #59298
NORTH 160' & WEST 48' TO THUNDER BAY RIVER
N 43° W 14.43' 50" MAPLE CLUMP #15410 (OW)
N 08° E 21.14' 13" MAPLE CLUMP #15410 (OW)
S 37° E 22.60' 20" MAPLE #15410 (OW)
S 15° W 20.56' 16" DEAD ASH #15410 (OW)
N 55° E 85.72' 26" MAPLE #59298

Retified by Peer Group
in accordance with P.A. 348
Chairman Matthew J. Dean
Date 11-4-2014

Signed by Travis L. Horrocks
Surveyor's Michigan License No. 68298

WITNESS TAGS & NAILS USED

Date 11/04/14