

SURVEY & REMONUMENTATION

APR 05 1996

COMMISSION

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Ottawa

Located In: Corner Code #

- | | | | | |
|---------------------------------------|---|--------------|-------|-----------------|
| | | Blendon Twp. | | |
| 1. Public Land Survey | T | 6N | R 14W | K-6, E 1/4 cor. |
| | T | | | Sec. 14 |
| | T | | | |
| | T | | | |
| 2. Property Controlling in Section | S | | | |
| | S | | | |
| 3. Miscellaneous Property in Sec. | S | | | |
| | S | | | |
| 4. Lot No. _____, Recorded Plat _____ | | | | |
| 5. Private Claims _____ | | | | |

RECORDED

95 NOV 29 PM 1:38

R. J. Hillman
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

I, Randal D. Feenstra, in a field survey on November 6, 1995

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. (1832)
Calvin Britain
12" Beech S31.5°W 17 lks.
12" Beech W70°E 35 lks.

LIBER 1, PAGE 601 (1972)
1" Pipe
T. Pole NE 46.0'
P. Pole SW 55.40'
St. Sign SE 39.95'
SE Cor. Porch Fndn. NW 105.90'

LIBER 2, PAGE 191 (1973)
3/4" Iron
Spike in 20" Oak WNW 111.68'
SE Cor. Porch Rndn. SW 105.90'
Nail in P. Pole SW 55.39'
Nail in T. Pole NE 46.23'

LIBER 4, PAGE 265 (1981)
C.I.M.
T. Pole NE 46.27'
P. Pole SW 35.42'
14" Apple SE 81.45'
SE Cor. Porch NW 105.62'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found: C.I.M. Accepted as a careful and faithful perpetuation of the position of the original corner.

Nail in SE side P. Pole SW 55.26'
Spike in S side 20" Oak WNW 111.58'

P.A. 340 OTTAWA COUNTY
PEER APPROVED 11/20/95
Randal D. Feenstra
RDF

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-6 C.I.M. in Gravel

Ottawa County Remon. Nail & Tag in S. side 24" Oak	283°	111.49'
Ottawa County Remon. Nail & Tag in NW side 7" Poplar	50°	76.20'
NE Cor. Fndn. to Hse. #5613	327°	132.09'
SW Cor. Fndn. to Hse. #5613	308°	121.22'

Centerline Baldwin St. and 56th Ave.



Signed by Randal D. Feenstra
37275

Date November 6, 1995

Surveyor's Michigan License No. _____