

SURVEY & REMONUMENTATION

APR 24 1995

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AM 11:45

COMMISSION
For corners in
OTTAWA

Deborah Robinson
REGISTER OF DEEDS
OTTAWA COUNTY, MI

(County)	Located In:	Corner Code ##
1. Public Land Survey	T 8N R 16W	G-9, SE Corner
	T _____ R _____	Section 21
	T _____ R _____	Spring Lake Twp.
	T _____ R _____	
2. Property Controlling in Section	S _____ T _____ R _____	
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, THOMAS E. JOINER in a field survey on 11-21- 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.


A. Description of original monument and accessories and/or subsequent restoration:
 05-27-1832 Liber 5, Pg. 262, 01-16-87
 Post set by John Mullet Ottawa County Cast Iron Monument
 N73°E 20 18" Hemlock NNW 90.65 SE Corner Foundation
 S20°W 8 15" Hemlock NW 75.41 Corner brick building face
 WSW 75.66 Corner brick building face
 SW 77.26 PK NE side of power pole
 SE 49.02 PK NE side of power pole
 NE 44.45 ζ Top of Hydrant

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Cast Iron Monument in Monument Box and accepted as a careful and faithful perpetuation of the position of the original corner.

Liber 5, Pg. 262, 01-16-87
 NNW 90.65 SE Cor. Foundation
 NW 75.41 Cor. Brick Bld. Face
 WSW 75.66 Cor. Brick Bld. Face
 SW 77.26 PK NE side of Power Pole
 SE 49.02 PK NE side of Power Pole
 NE 44.45 ζ Top of Hydrant

P.A. 345 OTTAWA COUNTY
 PEER APPROVED 12/12/94
Madon D. Hedewell



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Cast Iron Monument in Monument Box

ζ Top Operating Nut on Hydrant	Az. 64°	44.46
O.C. Remon Tag & Nail in NE side Guy Pole	Az. 138°	49.02
NE Cor. Brick Bdg. #1454	Az. 213°	77.20
O.C. Remon Tag & Nail in N side 42" Maple	Az. 260°	98.79
O.C. Remon Tag & Nail in NE side Power Pole	Az. 332°	38.77

Signed by Thomas E. Joiner Date 12-9-94
 Surveyor's Michigan License No. 18435