

**SURVEY &
REMONUMENTATION**

SEP 11 2007

SECTION

**OSCODA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970



For corners in
OSCODA
(County)

Located In: Corner Code #

- Public Land Survey T26N R1E G-7
- Property Controlling in Section S
- Miscellaneous S
- Property in Sec. S

JERI WINTON
OSCODA COUNTY
REGISTER OF DEEDS
08/29/2007 10:08:54AM
FEE: \$14.00
PAGES: 1 RCPT#: 5761
LC8-110 CORNER RECORDATION

APPROVED
County Remonumentation
Peer Review Group

Register of Deeds Stamp & File Number

- Lot No. , Recorded Plat
- Private Claims

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	13	17	16	15	14	13							
7	19	20	21	22	23	24							
8													
9	30	29	28	27	26	25							
10													
11	31	32	33	34	35	36							
12													
13													

I, Marvin E. Myers, P.S., in a field survey on June 4, 2007, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-7 Section Corner common to Sections 15, 16, 21, & 22 of T.26N.-R.1E.
1839 GLO William R. Coon Deputy Surveyor
Mon.- Set post Corner Sections 21, 22, 15, 16
Wit: Sp Pine 6" N35°E 14 lks (9.24)
Spr Pine 8" S30 ½°W 60 lks (39.60)

2001 unrecorded survey Frederick J. King PS #25852
Mon.- Fnd Rec GLO Mon
Wit: None given


1937 GLO Dependent Resurvey Guy R. Veal Cadastral Eng.
Mon.- Proportionate distance; there is no remaining evidence of the original or bearing trees.
Set a concrete monument, 24 ins. long, 6 ins. diam., 18 ins. in the ground, for cor. of secs. 15, 16, 21, and 22, with brass tablet, 3 ½ ins. diam., 3 in. stem, embedded in top and mkd.
Wit: A Norway Pine, 16 ins. diam., bears N. 81 ¾° E., 200 lks. (132.00) dist., mkd. T 26 N R 1 E S 15 B T.
A Jack Pine, 8 ins. diam., bears S. 15 ¾° E., 117 lks. (77.22) dist., mkd T 26 N R 1 E S 22 B T.
A Jack Pine, 5 ins. diam., bears S. 12° W., 50 lks. (33.00) dist., mkd. T 26 N R 1 E S 21 B T.
A Norway Pine, 12 ins. diam., bears N. 33° W., 206 ½ lks. (136.29) dist., mkd. T 26 N R 1 E S 16 B T.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-7 Section Corner common to Sections 15, 16, 21, & 22 of T.26N.-R.1E.
Found USGLO monument in good condition. Found no existing witnesses of record. Accepted USGLO as a careful and faithful reestablishment of the corner. Corner is 200'± South of Randall Road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-7 Section Corner common to Sections 15, 16, 21, & 22 of T.26N.-R.1E.
Mon - Left USGLO monument in place and placed two spikes along side for future magnetic detection
Wit:
S74W 41.84 Set N&T N side 21" twin Oak
N13W 17.52' Set N&T N side 8" R Pine
S60E 14.26' Set N&T SW side 23" Oak
N63E 10.35' Set N&T N side 5" J Pine
North 2'± Set carsonite post



Signed by Marvin E. Myers
Surveyor's Michigan License No. 31600

Date July 27, 2007
FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 197
REVISED MAY 14, 197
REVISED JAN. 198
ADAPTED FOR WORD PROCESSING MARCH, 199