


**SURVEY &
REMONUMENTATION**

SEP 11 2007

SECTION

**OSCODA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970



JERI WINTON
OSCODA COUNTY

For corners in
OSCODA
(County) Located in: Corner Code #

REGISTER OF DEEDS
08/29/2007 10:09:10AM
FEE: \$17.00
PAGES: 2 RCPT#: 5761
LC8-126 CORNER RECORDATION

- 1. Public Land Survey T26N R1E L7
- 2. Property Controlling S **APPROVED**
- in Section S
- 3. Miscellaneous S
- Property in Sec. S Peer Review Group

4. Lot No. REC 25 A0607, Recorded Plat

5. Private Claims

I, Marvin E. Myers, P.S., in a field survey on April 24, 2007, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-7 Section Corner common to Sections 14, 15, 22, & 23 of T.26N.-R.1E.

1839 GLO William R. Coon Deputy Surveyor
Mon.- Set post Corner Sections 22, 23, 14, 15
Wit: Cedar 10" S62 ½°E 18 lks (11.88)
Birch 16" N31°W 27 lks (17.82)

1885 Oscoda County Surveyor John Randall
Mon.- post
Wit: None given

1912 Oscoda County Surveyor C.O. Seeley
Mon.- Int'd 10 links (6.60) West of corner of Sec 14-15-22-23 prove to be Randall by affidavit of two persons who buried iron at Stake. Gov BT gone, but found some roots to correspond to position of Birch. Later proved said corner by measurement after locating corner of section 22, 23, 26, & 27 BT of this corner were found and stake found by Randalls field notes.
Wit: NBT Twin W Pine Stump S12°E 140 ½ lks (92.73)

1935 George D. Henning #2240
Mon.- Found Seeleys Witness and Plow Point buried flush in road
Wit: NBT White Pine 12" N49°30'W 161.67 lks (106.7)
Cedar Clump 4" N62°30'E 104.5 lks (68.97)
Metal Location Poster is on a Jack Pine on the West side of road. From which the corner bears SW 0.40± chains Poster bears witness data (26.40)

Part A continued on back: →

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-7 Section Corner common to Sections 14, 15, 22, & 23 of T.26N.-R.1E.

Found USGLO concrete block monument three feet North of centerline of Randal Road and fifteen feet East of centerline of Knott Road South and on the centerline of Knott Road North; found 6" Cedar S53°E 77.55; found Cedar Post South 33.09; found USGLO witness concrete monument with brass cap S60°W 65.89; found nail & tag 14" Spruce N59°W 52.48; found nail & tag in Wood Post N18°E 74.83; found nail & tag 12" Cedar with old face blaze S55°E 77.68 Accepted USGLO monument as a perpetuator of the original government corner.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-7 Section Corner common to Sections 14, 15, 22, & 23 of T.26N.-R.1E.

Mon - Left USGLO concrete block monument 3± N. of centerline of Randal Rd and 15± E of centerline of Knott Road South and on the centerline of Knott Road North--
Wit: 6" Cedar S53°E 77.55
Cedar Post South 33.09
USGLO witness concrete monument with brass cap S60°W 65.89
Nail & tag 14" Spruce N59°W 52.48
Nail & tag in Wood Post N18°E 74.83
Nail & tag 12" Cedar with old face blaze S55°E 77.68

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4						3			2	1
3													
4	7	8	9						10	11	12		
5													
6	13	17	15						16	14	13		
7													
8	19	20	21						22	23	24		
9													
10	30	29	28						27	26	25		
11													
12	31	32	33						34	35	36		
13													



Signed by Marvin E. Myers
Surveyor's Michigan License No. 31600

Date August 7, 2007