

**SURVEY &
REMONUMENTATION**

AUG 24 2006

SECTION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Oscoda Located in: _____ Corner Code # _____
(County)

Liber 7 pgs 247-248

FILED

At 9:11 o'clock A M
Date 8-14 2006

Clerk/Register of Deeds
Oscoda County, Michigan

Register of Deeds Stamp & File Number

1. Public Land Survey T 26 N R 1E K-6
T R
T R
T R
T R
2. Property Controlling S
in Section S
3. Miscellaneous S
Property in Sec. S

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Marvin E. Myers, in a field survey on Jan 23, 2006 hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration

K-6 T26N, R1E

Mon - Set Post
Wit: 8" Aspen N25°W 15 lks
6" Aspen S24°30'E 10 lks

Mon - Set Post
Wit: 12" W Pine Stp. S31°E 178 lks info

Mon - Fd old Stake remark NBT old stump nearly gone
Set 24"x1 1/4" well pipe at stake
Wit: 18" Yellow Pine S21°30'E 2.11 3/4 chains

County surveyor records no date
Mon - Fd. Seeleys iron & wit:

Wit: 18" Y Pine S21°30'E 2.11 3/4 chs.

1937 Guy Veal CE

Mon - Set Conc. Blk at seeley's iron & remains of Seeley's witness

Wit: Fd 18" Norway Stump S21°30'E 212 lks

Fd 12" Norway S22°W 140 lks

Fd 12" Norway N52°W 67 lks

Set Conc. Wit. Mon. West 50 lks

Wit: 19" Norway N25°15'E 333 lks

12" Norway S28°15'W 117 lks

1986 USFS Haase

(Sketch of survey)

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2								
3													
4	7	6	5	4	3	2	1						
5													
6	8	7	6	5	4	3	2	1					
7													
8	9	8	7	6	5	4	3	2	1				
9													
10	10	9	8	7	6	5	4	3	2	1			
11													
12	11	10	9	8	7	6	5	4	3	2	1		
13													

(History continued on back of this sheet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-6 T26N, R1E Found 5/8" bar in mon. box; found; USGLO Wit. Mon. West 32.96; found Nail & Tag #31605 in P. Pole S52°W 71.80; found Nail & Tag #31605 in 7" R. Pine N80°E 53.19; found Nail & Tag #31605 in P. Pole S78°E 34.87 Accepted 5/8" rebar as a the best available evidence of the position of the Original Government corner. Placed standard Oscoda County cap on 5/8" rebar in pavement monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-6 T26N, R1E

Mon - 5/8" bar with Standard Oscoda County cap in pavement monument box.

Wit: Fd USGLO Wit. Mon. West 32.96

Fd Nail & Tag #31605 in P. Pole S52°W 71.80


Fd Nail & Tag #31605 in 7" R. Pine N80°E 53.19

Fd Nail & Tag #31605 in P. Pole S78°E 34.87

APPROVED

County Remonumentation
Peer Review Group

Rec 31 July 06



Signed by *[Signature]*
Surveyor's Michigan License No. 31600

Date July 18, 2006