Received
PRESQUE ISLE COUNTY
01-09-2015 09:04 am.

PRESQUE ISLE COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Located in:	Corner Code #
PRESQUE ISLE (County)	METZ (Township)	
1. Public Land Survey	T 33N R 5E	I-11
	T___ R___	
	T___ R___	
	T___ R___	
2. Property Controlling	S___ T___ R___	
in Section	S___ T___ R___	
3. Miscelaneous	S___ T___ R___	
Property in Sec.	S___ T___ R___	

4. Lot No. _____ , Recorded Plat _____
5. Private Claims _____

Instrument Liber Page
201500000083 OR 558 939

201500000083
Filed for Record in
PRESQUE ISLE COUNTY
CATHY I. IDALSKI, REG OF DEEDS
01-09-2015 At 09:09 am.
LC-REMON 17.00
OR Liber 558 Page 939 - 940

Register of Deeds Stamp & File Number



I, Daniel T. Kibbe, in a field survey on July 7, 20 14, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

See Back Of Sheet for History

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

2014: Huron Engineering & Surveying 2014 Remon

Found 1" pipe & Cap MDNR 33981
References:
N08°W 9.90' 10" Maple 60d spike & tag#33981
N58°W 10.05' 18" Aspen 60d spike & tag#33981
S56°W 14.35' 10" Balsam 60d spike & tag#33981
S22°W 11.72' 8" Balsam 60d spike & tag#33981
S65°E 31' CL Mud Lake Hwy
Blue Carsonite marker 0.65' north of corner
SE witness to 16" Cedar has been cut down

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

2014: 1" pipe & Cap MDNR 33981
References:
N08°W 9.90' 10" Maple 60d spike & tag#33981
N58°W 10.05' 18" Aspen 60d spike & tag#33981
S56°W 14.35' 10" Balsam 60d spike & tag#33981
S22°W 11.72' 8" Balsam 60d spike & tag#33981
S65°E 31' CL Mud Lake Hwy
Blue Carsonite marker 0.65' north of corner

Ratified by Peer Group
In accordance with P.A. 345
Chairman
Date 11-04-2014

STATE OF MICHIGAN
DANIEL T. KIBBE
LAND SURVEYOR
No. 37278
LICENSED LAND SURVEYOR

Signed by _____ Date November 7, 2014

Surveyor's Michigan License No. 37278

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT. 1995