

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 NR 27 W

Dickinson

COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 15 and 16

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Cedar 12" S 43 E 22 links, marked 1/4 S NBT

Cedar 12" N 19 W 38 1/2 links, marked 1/4 S NBT

Distances measured from center of Brass Cap to NBT notch.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two original cedar bearing trees, one in good condition with scribe marks plain and one in fair condition with no identifying marks. Wood post in place.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 13 May 1957 with Clarence R. Ryberg

SURVEYORS SEAL

Henry S. Peterson
SIGNED Henry S. Peterson DATE 5/14/57
REGISTERED LAND SURVEYOR