

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 **003** PAGE **233**

For corners in IONIA Located In: Corner Code #
 (County)

1. Public Land Survey T8 N R5 W E-11
 T R
 T R
 T R

2. Property Controlling S T R
 in Section S T R

3. Miscellaneous S T R
 Property in Sec. S T R

STATE OF MICHIGAN
 IONIA COUNTY
 RECEIVED FOR RECORD
 16 NOV 95 4:26 P.M.
 DIANE M. ADAMS
 REGISTER OF DEEDS
 Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, MARINUS MULDER, in a field survey on AUGUST 23 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
THIS CORNER WAS FIRST ESTABLISHED BY U.S. DEPUTY SURVEYOR, ORANGE RISDON IN 1831. A WOOD POST WAS SET WITNESSED BY A 16" RED OAK SOUTH 6 LINKS AND A 10" WHITE OAK N 78° E 31 LINKS. THERE IS NO RECORDED DOCUMENTATION OF THIS CORNER BEING PERPETUATED BY THE COUNTY SURVEYOR.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
NO IRONS WERE FOUND AT THIS LOCATION WHICH FALLS AT THE INTERSECTION OF SCHAFFER ROAD (EAST-WEST) AND STRUBLE ROAD TO THE SOUTH. EXCAVATED ROAD WITH A BACK HOE AND FOUND A PILE OF STONES WITH REMAINS OF A WOOD STAKE IN THE CENTER 12" BELOW THE ROAD SURFACE CLOSE TO THE CENTERLINE INTERSECTION OF SCHAFFER AND STRUBLE ROADS. ACCEPTED THE STONE PILE AND STAKE REMAINS AS THE BEST AVAILABLE EVIDENCE OF THE PERPETUATION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
**SET A 3/4" X 24" STEEL ROD WITH A 2 3/4" DIAMETER CAP STAMPED "IONIA COUNTY P.S. 25863" IN PLACE OF THE WOOD REMAINS WITNESSED BY:
 CENTERLINE OF ROAD SIGN POST N 31° W 30.40 FEET
 NAIL & TAG NORTH SIDE 40" OAK S 68° W 38.00 FEET
 NAIL & TAG NORTHWEST SIDE POWER POLE N 75° E 84.55 FEET
 NAIL & TAG NORTHEAST SIDE 24" MAPLE S 45° E 37.27 FEET
 NAIL & TAG EAST SIDE 24" WALNUT N 28° W 52.37 FEET**

Ratified by Peer Group
 P.A. 345 Ionia County

Date Nov. 1, 1995
 Marinus A. Mulder, Chairman

Signed by Marinus A. Mulder Date 11-14-95

Surveyor's Michigan License No. 25863