

✓

**MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION**

LAND CORNER RECORD

T. 45N N.R. 27W


Marquette COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Sections 19-20-29-30

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7/19/66

WITNESSES TO CORNER..... 12" jack pine (S30 NBT) S 47° W 13.3'



16" jack pine (S29 NBT) S 72° E 30.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one original bearing tree; a 10" jack pine, down, burned with both faces and notch in evidence; bearing S56°E 38 links.

Found no evidence of use at this corner.

Corner lies in bottom of ravine.

Corner found by A. Klawiter, Party Chief, while making a Retracement Survey of this township.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 1/9/67
REGISTERED LAND SURVEYOR