


**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Montmorency (County)	Located In	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 33 T 30N R 2E	5
	S 33 T 30N R 2E	7
3. Miscellaneous Property in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No: _____	Recorded Plat: _____	
5. Private Claims: _____		

Register of Deeds Stamp & File Number

I, Carl T. Kiiskila, in a field survey on April 30, 2001 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**



**A. Description of original monument and accessories and/or subsequent restoration:**

5- Donald E. Marlatt R.L.S. #18660 Aug. 1982 cert. of survey. Set 1/2" rod and cap Wit: N70°W 8" Maple 12.3', South 5" Maple 25.35', N75°E 10" pine stub 10.3'

7-This corner position was not established during the original government survey.

Donald E. Marlatt R.L.S. #18660 Aug. 1987 cert. of survey. Found 1/2" rod and cap Wit: N70°W 8" Maple 12.3', South 5" Maple 25.35', N75°E 10" pine stub 10.3'

**B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:**

5- Re-established the Northwest corner of the Southwest quarter of the Northeast quarter of section 33 as per B.L.M. instructions for the subdivision of a section.

7- Found 1/2" capped iron Beauregard L.S. #18654

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

5- Set 5/8" X 32" reroed with P.S. cap #33981  
Wit: 7" Oak South 21.85'  
8" Maple N65°E 13.62'  
22" Red Pine S60°E 51.57'  
10" Oak N54°E 39.43'  
Carsonite Post North 1'±

7- Found 1/2" capped iron Beauregard L.S. #18654  
Wit: 3" Oak S89°W 44.87'  
5" White Pine N64°E 67.78'  
5" Maple S60°E 60.06'  
12" Oak S39°E 80.69'  
Centerline of North-South gravel road West 2'±  
Carsonite post West 33'±

Signed by:

Carl T. Kiiskila

Date:

3-7-02

Surveyor's Michigan License No.: 33981

