

Montmorency County Remonumentation

Liber 12 Page 64

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Montmorency</u> (County)	Located In:	Corner Code #:
1. Public Land Survey	T <u>31N</u> R <u>4E</u>	<u>A-7</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____

RECEIVED
 MONTMORENCY CITY
 REGISTER OF DEEDS
 DEC 28 9 06 AM '93
 A. PANKAH-AGELROY

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	13		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Larry G. Beauregard in a field survey on August, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A-7) **NOTE: THIS TWP. LINE IS A RESURVEYED LINE BY BURNHAM.**
 GLO Post set by Hiram Burnham April 1850.
 Wits: Spruce Pine 10" S 65° W 25 links Spruce Pine 8" N 75° W 16 links
 Carl R. Johnson P.S. #30083, (DNR Surveyor) in April 1992, fnd. 1 1/4" pipe 20'± West of Miller Creek Road C/L & accepted it as the true position of the corner location.
 (Placed DNR Red Top Post along side) Act 74 on file Rec. L. 1, Page 474.
 Wits: (Red Pine 12" N 49° W 15.7') (Jack Pine 10" N 78° E 37.3') (Jack Pine 8" S 51° E 49.2') (Oak 5" S 18° W 39.4').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A-7) Fnd. 1 1/4" pipe 20'± West of Miller Creek Rd. & wits. Red top post along side cor. No I.D. cap (Placed 3" dia. Aluminum cap marked Montmorency Co. Re-Monumentation corner on same.)



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A-7) Sec. Cor. Comm. to Sec. 13 & 24, T31N, R3E & Sec's 18 & 19, T31N, R4E
 1 1/2" pipe & Re-Mon. cap #18654. Accepted as the best available evidence of the original government corner, approved by the Peer Group on September 24, 1993.
 N 49° W 15.7' (R) to blaze, 16.12' to spike, 12" Norway (R) NBT
 S 18° W 39.4' (R) to blaze, 39.68' to spike, 5" Oak (R) NBT
 S 51° E 49.2' (R) to blaze, 49.65' to spike, 9" J. Pine (R) NBT
 N 78° E 37.3' (R) to blaze, 37.85' to spike, 11" J. Pine (R) NBT
 (Placed 20 penny spike & P.S. tag #18654) (typ)

Signed by Larry G. Beauregard Date 12-27-93
 Surveyor's Michigan License No. 18654