

SURVEY & REMONUMENTATION

APR 24 1995

OTTAWA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

RECORDED

For **COMMISSION**

Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC 15 AM 11:48

Ottawa (County)	Located in:	Corner Code #
1. Public Land Survey	T <u>6N</u> R <u>15W</u>	L-9
	T _____ R _____	(N 1/4 cor., Sec.
	T _____ R _____	25, Olive Twp.)
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

D. J. Koning
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

I, Douglas J. Koning, in a field survey on December 8, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/of subsequent restoration:

L-9 Government Notes Set Post May 1832 By Calvin Britain D.S. Hemlock 24" N28°W 31 Links Leo 4" S2°E 22 Links	L.C.R.C. Liber 1, Page 385 May 1972 L-9 Found iron Nail in face of Pwr. pole NE 37.89' Nail in face of St. Sign N 28.27' Nail in face of Pwr. pole SE 70.44' Nail in face of Pwr. pole SW 51.35'	L.C.R.C. Liber 5, page 324 August 1988 L-9 Set CIM Pwr. pole NNE 38.3' Pwr. pole SE 71.2' Tel. pole SW 51.8'
	L.C.R.C. Liber 1, page 763 November 1972 L-9 Nail in Pwr. pole SW 51.32' Nail in Pwr. pole NNE 37.88' Nail in Pwr. pole SE 71.26' SE cor. House Foundation NW 96.68'	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.


L-9 Found cast iron monument in box
Found PK in E. side Pwr. pole NNE 38.27'
Found Nail in W. side Pwr. pole SE 71.24'
SE corner house NW 96.64'

P.A. 345 OTTAWA COUNTY
PEER APPROVED 12/12/94
Robert D. Nedewold

This marker is accepted as a careful and faithful perpetuation of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

L-9 Cast Iron Monument in Box (1' S. & 1' W. Centerline "x" Road E., W., & S.)
Set O.C. Remon Nail & Tag W. side Pwr. pole S20°E 71.24'
Set O.C. Remon Nail & Tag E. side Pwr. pole N20°E 38.22'
Set O.C. Remon Nail & Tag S. side 12" Maple N60°W 87.69'
SE cor. Block Foundation House N20°W 96.64'
SE cor Block Foundation House #10004 Port Shl. S35°W 105.26'



Signed by Douglas J. Koning
Surveyor's Michigan License No. 35995

Date December 12, 1994